

Lam Research
SEZ SP323 & DV34
Defect Review

Tool overview:

SEZ SP323 defect review

Summarized defect:

1. MED1 & MED 2: Pump surface corrosion, Emergency drain button broken, Door connection damaged.
2. MED 3: Door connection broken, Emergency drain button damaged, Door override button damaged, Cabinet inside messy.
3. Process chamber chuck edge damaged, Main body inside messy and dirty.
4. The cleaning of the machine needs to be handled by yourself, and the spare parts need to be overhauled or replaced (such as filters, etc.).






Tool overview:

SEZ DV34 defect review

Summarized defect:

1. Process chamber chuck missing.
2. Filter is dirty and the spare parts need to be overhauled or replaced. (such as filters, etc.)
3. The crate C7(ASSY BOXA) package surface is dirty and wet.





