Make	Canon Stepper
Model	FPA - 2000 i1

2. Configuration of equipment

1) Configuration			
Main Unit	FPA-2000 i1	1	
Electrical	3Ø AC 200V 50/60Hz	1	
Rated power	15.3 KVA	1	
Reticle Size	5", Canon STD	1	
Wafer Size	"6	1	
Wafer Feeder	Type-L	1	
PA Unit	6", O.F Type	1	
Chamber	TBW-CD50W	1	
Illuminator	FPA-2000 i line	1	
Console version	V 5.5A	1	
A Scope	i-line, TTL	1	
Θ/Z-Tilt Unit	Piezo Stack	3 (L,M,R)	
Support Mount	Servo Passive Damper	4	
Lamp House	1.5KW	1	

3. Missing & Change Part List

1) Missing Part

a. PD-Box Out Side Cover : Front 1ea, Back 2ea

b. Control Rack Out Side Cover : Front 1ea

4. Comment

1) Working Condition.