Tool Configuration / Specifications

PROCESS OPTIONS
Option B - P/N 5110C-2
Option A - P/N 5110C-1 N2 Spin Solvent Dispense
Resist dispense (Tank required)
Spread speed spin Final high speed spin Spin dry (No N2)
  Resist dispense
  Spread speed spin
  Final high speed spin
Option C - P/N 5110C-3
Solvent dispense (tank required) N2 Spin
Resist dispense
Spread speed spin Final high speed spin
EQUIPMENT OPTIONS
-Extra Resist Pumps P/N 0967
Note: The 5110C can have up to total of 4 dispenses Example: You can have 4 resist dispenses w/no N2 blow or solvent dispenses or 2 resist dispenses and 1 solvent and 1 N2 blow.
-3 gallon stainless steel tanks with metal sheathed teflon supply lines for solvents
P/N 0066 For HMDS, and Xylene with Viton seals P/N 0070 For N-Butyl Acetate, Acetone, EGMEA and Alcohols with EPR seals. See page 67 for chemical compatability table.
-Extra loading Paddle
-Spares Kit P/N 001525
-Pre-pump filter for positive or negative resist P/N 0255
-Additional vacuum chucks
-Small volume, disposable cartridge dispense system for multiple dispense applications

The information contained in this data sheet is, to our knowledge, accurate. We do not warrant the completeness or accuracy of the information contained herein. Any offer by you to purchase the equipment described in this data sheet shall be subject to the terms and conditions of sale.